

INSTRUCTIONS

2019-01-15



LEFT TANK CAP

GENERAL

Kit Numbers

57300149, 57300150, 57300151, 57300165, 57300185, 57300186, 57300216, 57300236

J06467

Models

For model fitment information, see the P&A retail catalog or the Parts and Accessories section of www.harley-davidson.com (English only).

INSTALLATION

NOTE

DO NOT pry the existing left tank cap off the tank. The adhesive is part of the base and not sold separately.

- 1. To remove original left tank cap, press down and turn the existing left tank cap counterclockwise to remove.
- When installing, position cap so that the tabs align, press down and turn the cap clockwise to lock. There is a 20° variance on the cap to allow for proper alignment on the tank.

CARE AND CLEANING GUIDELINES FOR BRASS PARTS

Cleaning Instructions

- 1. Verify part is dry and free of dirt or debris.
- Place a small amount of Harley-Davidson[®] Chrome Clean
 Shine on a microfiber cloth or detailing swab.
- Using light pressure, rub the brass parts with the microfiber cloth. For hard to reach places or grooves, use the detailing swab.

Obtaining a Bright Finish

Brass parts will naturally age and darken with time. If a bright brass finish is preferred, place some Harley-Davidson Bare Metal Polish on a microfiber cloth and lightly rub on the brass parts until they reach the desired brightness.

Slowing the Natural Aging Process

To slow the aging process of the brass parts, place a small amount of Harley-Davidson Glaze Poly Sealant on a microfiber cloth or detailing swab, and lightly rub on the parts until the sealant has soaked in.

Precautions

 Use of non-recommended cleaning, polishing and protective products will result in the removal of the aged finish from the brass parts.

- Prolonged contact with certain items (hands, gloves, boots, dust, etc.) and exposure to the elements will also alter all surface finishes and is NOT considered a defect.
- Avoid cleaning parts with abrasive and aggressive chemicals and abrasive cleaning pads.
- · Avoid ammoniated products and bleach.
- Prolonged exposure to water will alter the brass finish. Wipe down parts after contact with water.
- Excess rubbing may lighten the surface appearance of the part.




Figure 1. Left Tank Cap Alignment Tabs